



THE ESSENTIAL PART OF YOUR SOLUTION

Melting powder III

Artikel No.: 3140400203

Smooth melting precious metals residues or waste!

When smooth melting, precious metal-bearing residues or waste, without previous driving off impurities, are fused together.

Smooth melting is applied even when bare remnants of precious metal alloys are melted, to establish this semi-component or bars. Here, it is particularly important that the metal remains are really clean and free of debris

Usual amount to melting: approx. 20-30% of the weight of the metal on enamel powder admit III.